


FIG. I



F1G. 2




FIG. 3




FIG. 4

5/8

	L=	7[L=3	 L=13	 L=25
ZONE 1			630	 630	 630
ZONE 2			617	616	 615
ZONE 3			620	 620	 620
ZONE 4			617	 .6 1 5	 614
ZONE 5			619	 619	 619

FIG. 5




FIG. 6




FIG. 7





FIG. 8






FIG. 9